

APPENDIX A

NOTICE OF VIOLATION

Mississippi Power and Light Company  
Grand Gulf

License No. CPPR-118

Based on the NRC inspection May 27-30, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion V of Appendix B to 10 CFR 50, implemented by Mississippi Power and Light Company's PSAR, Section 17.1.5.2 Bechtel's activities affecting quality shall be accomplished in accordance with instructions, procedures and drawings. Bechtel Procedure WP/P-C-24, and Specification No. 9645-C-103.1 states that the responsible field engineer shall obtain appropriate approval prior to cutting rebar.

Contrary to the above, on May 28, 1980, the inspector observed electricians cutting rebar (by drilling through) in the base of diesel generator QIP75-E001B. The inspector was advised that they were instructed to cut through the rebar and then enter the fact in the rebar cut log.

This is an infraction.

8010010046