


me

Telephone 617 366-9011

TWX
710-390-0739

WYR-80-101
B.4.1.1

YANKEE ATOMIC ELECTRIC COMPANY



20 Turnpike Road Westborough, Massachusetts 01581

August 29, 1980

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Attention: Mr. Boyce H. Grier, Director

References: (a) License No. DPR-3 (Docket No. 50-29)
(b) USNRC Letter to YAEC dated July 31, 1980
IE Bulletin 80-19

Dear Sir:

Subject: Response to Reference (b), "Failure of Mercury-Wetted
Mercurix Relays in Reactor Protective Systems"

Reference (b) required that we determine whether or not Mercury wetted
relays are used in the Reactor Protective System (RPS).

We have determined that Mercury-Wetted Relays are not used in the RPS;
therefore, no further action is necessary.

The following information is submitted in response to your request for
estimates of manpower expended in the review, preparation of reports and
corrective actions required by this bulletin:

<u>Manpower Requirements</u>	<u>Hours</u>
Bulletin Research and Response	5
Corrective Actions	None Required

The information requested comprises only a small fraction of the
information necessary to do an accurate value/impact assessment. An
adequate determination of the safety improvement as a result of this
document is not included.

8010010198

Q


U. S. Nuclear Regulatory Commission
Attention: Mr. Boyce H. Grier

August 29, 1980
Page 2

We trust you find this information satisfactory; however, should you desire additional information, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY



D. E. Moody
Manager of Operations

BLD/dln