

Tic

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-5001

SHIELDS L. DALTROFF
VICE PRESIDENT
ELECTRIC PRODUCTION

August 27, 1980


IE Bulletin 80-19

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Grier:

Your letter of July 31, 1980, forwarded IE Bulletin 80-19 on "Failures of Mercury-Wetted Matrix Relays in Reactor Protective Systems of Operating Nuclear Power Plants Designed by Combustion Engineering". Item 1 of the Bulletin required a review of our facility to determine whether or not mercury-wetted relays are used in the Reactor Protection System (RPS). Our review has determined that no such relays are used for this application at Peach Bottom, therefore, no response is needed for the remaining items in this Bulletin. Approximately two man-days were expended in preparation of this response.

Very truly yours,



cc: US Nuclear Regulatory Commission
Office of Inspection & Enforcement
Division of Reactor Operations Inspection
Washington, DC 20555

8010020203

Q