U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

Report No.	50-286/80-06	
Docket No.	50-286 License No. DPR-64 Safeguards	Group 4
Licensee:	Power Authority of the State of New York	
	10 Columbus Circle	
	New York, New York 10019	•
Facility Na	Name: Indian Point 3 Nuclear Power Plant	
Inspection	At: Buchanan, New York	
Inspection	Conducted: June 15-20, 1980	
Date of Las	Oct 23-26;	
Type of Ins	espection: Unannounced, Physical Security	
Inspectors:	W. Madden, Physical Protection Inspector	7-11-80
	w. madden, Physical Protection Inspector	date
		date
		-
A	D. 1: 6: (date
Approved by	James W. Devlin, Chief, Security and Investigations Section, Safeguards Branch	date
Inspection '	Summary: Unannounced, Physical Protection Inspection o	n June 15-20, 1980
Areas Inspe	ected: Included a review of Security Plan: Security Pro	gram Audit: Security
Urganization	on; Protected Area Physical Barriers; Vital Area Physica trols (Identification, Authorization and Badging), (Sear	1 Barriers: Lighting:
(Vital Area:	as); Alarm Stations; Detection Aids; Assessment Aids: Con	mmunications:
and Combinat	d Maintenance; Compensatory Measures; Power Supply; Respections; Records and Reports; and a review of Licensee Pr	onse; Locks, Keys
Procedures.	. The inspection involved 49 inspector-hours on site by	one NRC Inspector.
during offst	tion began during non-regular hours and 11 inspection-househift periods.	urs were accomplished
Results: Th	The licensee was found to be in compliance with NRC requi	irements in 17 of
the 21 areas	as inspected. Five apparent items of noncompliance were	noted as follows:
lock system	ate protected area barriers (See paragraph 7); 2. Inadequent component (See paragraph 8); 3. Outdated authorization	listing (See
paragraph 10	10); 4. Tailure to wear photo-ID badges (See paragraph 16 ion System component failure (See paragraph 15).	0); and 5. Detection
arretuare	on a seem component rarrare (see paragraph 157.	