

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 0 | R | T | N | P | 1 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5

CON'T  
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | - | 3 | 4 | 4 | 4 | 7 | 0 | 7 | 0 | 9 | 8 | 0 | 8 | 0 | 8 | 0 | 7 | 8 | 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
5 2 | NO. 80-14: DURING FIELD VERIFICATION, A SEISMIC RESTRAINT WAS FOUND TO BE |  
5 3 | INSTALLED INCORRECTLY. THE RESTRAINT WAS FOR THE CONTROL ROOM EMERGENCY |  
5 4 | VENTILATION SYSTEM TRAIN "A" COOLING COIL. THE TRAIN "B" COOLING COIL WAS |  
5 5 | OPERABLE AND AVAILABLE FOR USE. |

0 9 | SYSTEM CODE | S | G | 11 | CAUSE CODE | B | 12 | CAUSE SUBCODE | C | 13 | COMPONENT CODE | S | U | P | P | O | R | T | 14 | COMP SUBCODE | B | 15 | VALVE SUBCODE | 2 | 16

17 | LER NO REPORT NUMBER | 9 | 0 | 21 | EVENT YEAR | 9 | 0 | 22 | SEQUENTIAL REPORT NO. | 0 | 1 | 4 | 24 | OCCURRENCE CODE | 1 | 0 | 3 | 25 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32

ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NRC-4 FORM SUB. | N | 24 | PRIME COMP SUPPLIER | A | 25 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 5 | THIS OCCURRENCE WAS CAUSED BY IMPROPER INSTALLATION DURING CONSTRUCTION. |  
1 6 | THE RESTRAINT WAS REMOVED AND REINSTALLED IN THE CORRECT LOCATION. |

1 3 | FACILITY STATUS | X | 28 | % POWER | 1 | 0 | 0 | 0 | 29 | OTHER STATUS | ALL MODES | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | ENGINEER WALKDOWN | 32

1 8 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 0 | 37 | TYPE | 2 | 38 | DESCRIPTION | NA | 39

PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43

PUBLICITY ISSUED DESCRIPTION | N | 44 | DESCRIPTION | NA | 45

NAME OF PREPARER John C. Perry PHONE 503/556-3713, ext.228