1710 DUKE POWER COMPANY PEGICIA POWER BUILDING THANTA, GIL 422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242 0 AUG 8 A9: 42 WILLIAM O. PARKER, JR. VICE PRESIDENT TELEPHONE: AREA 704 STEAM PRODUCTION 373-4083 August 5, 1980 Mr. James P. O'Reilly, Director U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303 Re: RII:JPO McGuire Nuclear Station Docket Nos. 50-369 and 50-370 Dear Mr. O'Reilly: In response to your letter of April 4, 1980 which transmitted IE Bulletin 79-03A, we wish to advise that a review of McGuire Nuclear Station's piping specifications has been conducted. Duke Power Company has not used SA-312, A-312, Type 300 Series fusion welded pipe in safety-related systems at greater than 85 percent of Code allowable pressure stresses. No future use above this limit is planned. Very truly yours, William O. Parker, Jr. RWO:vr cc: NRC/OIE Division of Reactor Construction Inspection.

OFFICIAL COPY

0