Georgia Power Company Post Office Box 4545 Atlanta, Georgia 30302 Telephone 404 522-6060



File: X7BG03-M11

Log: GM-692

Southern Company Services, Inc. Post Office Box 2625 Birmingham, Alabama 35202 Telephone 205 870-6011

September 12, 1980

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region II - Suite 3100 101 Marietta Street, NW Atlanta, GA 30302

Attention: Mr. James P. O'Reilly

Reference: 59-424, 50-425 - Defective Bolting Materials from Southern

Bolt and Fastener Company

Gentlemen:

On August 14, 1980 a potential deficiency was reported concerning failure of bolting materials supplied by Southern Bolt and Fastener Company. Since this date, Georgia Power Company has placed on hold all known material received from Southern Bolt and Fastener Company. Georgia Power Company is still conducting a review to determine if any other additional defective material has been received.

It is anticipated this review will be concluded and a final report filed with the NRC by November 15, 1980.

This response contains no proprietary information and may be placed in the NRC Public Document Room upon receipt.

17 471

Doug Dutton

CWH: tp

xc: U. S. Nuclear Regulatory Commission Attn: Victor Stello, Jr., Director Office of Inspection and Enforcement Washington, DC 20555

M. D. Hunt, NRC - Region II

B019

Mr. James P. O'Reilly Defective Bolting Materials from Southern Bolt and Fastener Company September 12, 1980 Page 2

xc: J. H. Miller, Jr.
W. E. Ehrensperger
F. G. Mitchell, Jr.
R. J. Kelly
C. F. Whitmer
R. E. Conway
D. E. Dutton
J. T. Beckham, Jr.
R. W. Staffa
K. M. Gillespie
L. T. Gucwa
C. R. Miles, Jr.
E. D. Groover
D. L. McCrary
R. A. Thomas
O. Batum
J. A. Bailey
M. Z. Jeric

B. L. Lex