

APPENDIX A  
NOTICE OF VIOLATION

Greater Southeast Community Hospital  
Washington, D.C. 20032  
License No. 08-11182-01

Docket No. 30-1334

Based on the results of an NRC inspection conducted on March 12, 1980, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC license as indicated below:

Condition 16 of your license requires that licensed material be possessed and used in accordance with the statements, representations and procedures contained in your license application dated August 30, 1977.

Item 16 of the "Radioisotope Laboratory Routine Safety Procedures", on page 8 of Appendix F of your application, requires that syringe shields be used for preparation and administration of radioactive material in millicurie quantities.

Contrary to this requirement, on March 12, 1980, individuals prepared patient doses in millicurie quantities without using syringe shields.

This is an infraction.