

DUKE POWER COMPANY

POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 18, 1980

25 12:41

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Subject: McGuire Nuclear Station
Docket No. 50-369

Re: RII:WPA
50-369/80-04

Dear Mr. O'Reilly:

Please find attached a supplemental response to the item of noncompliance identified in IE Inspection Report 50-369/80-04. This letter supplements my responses of June 5, 1980 and June 30, 1980.

Very truly yours,



William O. Parker, Jr.

LJB:scs
Attachment

8009240 206

DUKE POWER COMPANY
MCGUIRE NUCLEAR STATION

Supplemental Response to IE Inspection Report 50-369/80-04

Response

The evaluation of additional hangers for proper torque as discussed in my letter of June 30, 1980 has been completed. Fifty additional hangers were inspected for proper torque. Six of these hangers did not meet the torque requirements, therefore, all hangers which have been signed off by the QC inspector responsible for the inspection of RHR support ND-H76 will be reinspected. This inspection will be completed and all nonconforming items associated with these hangers will be corrected by August 15, 1980.