

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

HQ: Central file

JUN 20 1975

Commonwealth Edison Company
ATTN: Mr. Byron Lee, Jr.
Vice President
P. O. Box 767
Chicago, Illinois 60690

Docket No. 50-10

Gentlemen:

This refers to the inspection conducted by Messrs. Fisher and Knop of this office on May 13, 14, and 20, 1975 of activities at Dresden Unit 1 authorized by NRC Operating License No. DPR-2 and to the discussion of our findings with Mr. Stephenson and members of his staff at the conclusion of the inspection.

A copy of our report of this inspection is enclosed and identifies the areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, interviews with plant personnel, and observations by the inspector.

During this inspection, it was found that certain of your activities appear to be in noncompliance with NRC requirements. The item and reference to the pertinent requirements are listed under Enforcement Action in the Summary of Findings Section of the enclosed inspection report.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice, a written statement or explanation in reply, including: (1) corrective steps which have been taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

Based upon discussion with your management personnel at the conclusion, we understand that you plan to:



8009250 559

P

JUN 20 1975

Commonwealth Edison Company

- 2 -

1. Determine whether a safety analysis was performed to evaluate the possible effects of routinely overflowing the resin and sludge tanks.
2. Make core borings near the resin and sludge vaults to determine whether vault leakage has occurred.

We will examine these matters during a future inspection.

In accordance with Section 2.79C of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this notice, the enclosed inspection report, and your response to this notice will be placed in the NRC's Public Document Room. If this report contains any information that you or your contractors believe to be proprietary, it is necessary that you make a written application to this office, within twenty days of your receipt of this notice, to withhold such information from public disclosure. Any such application must include a full statement of the reasons for which it is claimed that the information is proprietary, and should be prepared so the proprietary information identified in the application is contained in a separate part of the document. Unless we receive an application to withhold information or are otherwise contacted within the specified time period, the written material identified in this paragraph will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely yours,

Gaston Fiorelli, Chief
Reactor Operations Branch

Enclosure:

IE Inspection Report
No. 050-010/75-10

cc: B. B. Stephenson
Station Superintendent, w/encl

bcc: PDR
Local PDR
NSIC
TIC
A. Roismar