

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

*Klactor Failure
br.*

APR 23 1976

Commonwealth Edison Company
ATTN: Mr. Byron Lee, Jr.
Vice President
P.O. Box 707
Chicago, Illinois 60690

Docket No. 50-10
Docket No. 50-237
Docket No. 50-249

Gentlemen:

This refers to the inspection conducted by Messrs. P. H. Johnson, R. C. Knop, R. D. Martin, H. B. Kistar and J. E. Kohler of this office on March 23, 25-26, and 29-31, 1976, of activities at Dresden Nuclear Power Station Units 1, 2 and 3 authorized by NRC Operating Licenses No. DPR-2, No. DPR-19 and No. DPR-25 and to the discussion of our findings with Messrs. Roberts and Abel and other of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described under Enforcement Items in the Summary of Findings section of the enclosed inspection report.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.



POOR ORIGINAL

8009250 563

P

Commonwealth Edison
Company

- 2 -

APR 23 1976

Noncompliance identified through your management control system and corrected in a timely manner is described under Other Significant Items in the Summary of Findings section of the attached inspection report. We have no further questions regarding these matters at this time.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this notice, the enclosed inspection report, and your response to this notice will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this notice, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely yours,

G. Fiorelli, Chief
Reactor Operations and
Nuclear Support Branch

Enclosure:
IE Inspection Reports
No. 050-010/76-06
No. 050-237/76-06 and
No. 050-249/76-05

cc w/encl:
B. B. Stephenson,
Station Superintendent

bcc w/encl:
PDR
Local PDR
NSIC
TIC
Anthony Roisman, Esq.,
Attorney
HQ Reproduction

POOR ORIGINAL