



**Commonwealth Edison**  
Zion Generating Station  
Shiloh Blvd. & Lake Michigan  
Zion, Illinois 60099  
Telephone 312/746-2084

DSB

September 22, 1980

Mr. James G. Keppler  
Region Director  
Directorate of Regulatory Operations  
Region III  
U. S. Nuclear Regulatory Commission  
Glen Ellyn, IL 60137

Reference: Zion Generating Station  
Docket No. 50-295/DPR-39  
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/80-39 for Zion Generating Station. This occurrence was found by internal audit on September 3, 1980.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b.2., which states that conditions leading to operation in a degraded mode permitted by a limiting condition for operation requires a 30 day written report.

Very truly yours,

K. L. Graesser  
Superintendent  
Zion Station

cc: J. Kohler

Enclosure: Reportable Occurrence Report No. 50-295/80-39

A002  
S111

SEP 23 1980

S 8010020 532