

APPENDIX A

NOTICE OF VIOLATION

Northeast Nuclear Energy Company

Docket Nos. 50-245
50-336

Based on the results of an NRC inspection conducted on March 30 - May 3, 1980, it appears that certain of your activities were not conducted in full compliance with the conditions of your NRC License as indicated below. Item A has been categorized as an Infraction and Item B has been categorized as a Deficiency. Item A refers to License No. DPR-21; item B refers to License No. DPR-65.

- A. Unit 1 Technical Specification 6.8.1 states in part, "Written procedures shall be established, implemented and maintained..."

Health Physics Procedure - 901, Dosimetry and Exposure Control, Revision 6, dated April 3, 1980, paragraph 5.2.2.1 states, "All Station, Contractor and Utility personnel shall be required to wear a FB/TLD badge in areas with dose rates greater than 0.5 mrem/hour."

Contrary to the above, on April 23, 1980, a station employee was observed working in the Unit 1 Reactor Building, a radiation area with dose rates greater than 0.5 mrem/hour, without a personal film badge/thermoluminescent dosimeter. (50-245)

- B. Unit 2 Technical Specification 3.7.8.1 states, "All hydraulic snubbers listed in Table 3.7-1 shall be operable." Surveillance Requirement 4.7.8.1 states, in part, "(a) Hydraulic snubbers shall be demonstrated operable by performance of the following augmented inservice inspection program. (b) Each hydraulic snubber with seal material not fabricated from ethylene propylene or other material demonstrated compatible with the operating environment shall be determined operable at least once per 31 days by a visual inspection of the snubber."

Contrary to the above, the Reactor was operated in Modes 1 through 4 during a period from December 4 through 22, 1979, with two hydraulic snubbers (Hanger numbers 413082 and 490031) listed in Table 3.7-1 which have seals fabricated from material other than ethylene propylene, which were not demonstrated to be compatible with the environment and had not be inspected within the previous 31 days.

8010020 767

APPENDIX B

NOTICE OF VIOLATION

Northeast Nuclear Energy Company

Docket No. 50-245

Based on the results of an NRC inspection conducted on March 30 - May 3, 1980, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC License as indicated below. The item has been categorized as an infraction.

THESE PARAGRAPHS, CONTAINING 10 CFR 2.790 INFORMATION, NOT FOR PUBLIC DISCLOSURE, ARE INTENTIONALLY LEFT BLANK.