



Me
Metropolitan Edison Company
Post Office Box 480
Middletown, Pennsylvania 17057

Writer's Direct Dial Number

September 15, 1980

TLL 462

Office of Inspection and Enforcement
Attn: Mr. Boyce H. Grier, Director
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-2)
Operating License No. DPR-73
Docket No. 50-320
IE Bulletin 79-28

This letter is submitted as a result of the requirements of IE Bulletin 79-28, and is subsequent to our letter of July 9, 1980 (TLL 335).

The subject Bulletin, "Possible Malfunction of Namco Model EA180 Limit Switches at Elevated Temperatures", addresses a possible failure mode due to a manufacturing deficiency for a given production lot of this switch.

In accordance with Action 1 of this bulletin, we have reviewed the system in the Unit 2 facility to determine if the subject switches are utilized. We have determined that no Namco Model EA180 limit switches are utilized in this facility. Therefore, Actions 2 and 3 of this bulletin are not applicable to TMI-2. This constitutes our entire and complete response to this bulletin.

Sincerely,

G. K. Hovey
Director, TMI-2

GKH:SDC:dad

cc: John T. Collins
Bernard J. Snyder