

**Midwest  
Inspection  
Service, Ltd.**

TIC

P. O. Box 3081 • Green Bay, Wisconsin 54303 • Telephone: 414/336-3554

September 22, 1980

Mr. James Keppler, Director  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reference: IE Bulletin No. 80-22


Dear Mr. Keppler:

In response to IE Bulletin No. 80-22, Midwest Inspection Service, Ltd. respectfully submits the following information.

- ITEM 1: Midwest Inspection Service, Ltd. does not have AI Model 200-520-008 "quick disconnect" assemblies in our possession.
- ITEM 2: Not applicable
- ITEM 3: Not applicable
- ITEM 4: Not applicable
- ITEM 5: As a part of our personnel inspection on projects, and as part of our "house cleaning" the importance of physical surveys is always discussed and evaluated.

This report is furnished in accordance with request made in your letter dated September 16, 1980.

Sincerely yours,



Donald Paschen  
President

DP/sg

cc: Director  
Division of Fuel Facility and Material Safety Inspection  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Washington, D.C. 20555

SEP 25 1980

8010200 081

