

Thomas J. Martin
Vice President
Engineering and Construction

Public Service Electric and Gas Company 80 Park Place Newark, N.J. 07101 201/430-8316

September 17, 1980

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Grier:

NRC BULLETIN NO. 80-19, REVISION 1
FAILURES OF MERCURY - WETTED MATRIX RELAYS
IN REACTOR PROTECTIVE SYSTEMS OF OPERATING
NUCLEAR POWER PLANTS
DESIGNED BY COMBUSTION ENGINEERING
NO. 1 AND 2 UNITS
HOPE CREEK GENERATING STATION

In reply to IE Bulletin No. 80-19, Revision 1, dated
August 15, 1980, we offer the following:

We have reviewed the subject bulletin and have concluded
that the C. P. Clare Model #G2X-1011 Mercury - Wetted Relays
are not used in the logic matrix of the reactor protective
system.

Should any additional information be desired, we will be
pleased to discuss it with you.

Very truly yours,

TJM/RM

CC: Director,
Division of Reactor Operations Inspection
Office of Inspection and Enforcement
Nuclear Regulatory Commission
Washington, D. C.

8010270116

Q