

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV

TIC

611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

September 2, 1980

In Reply Refer To: Docket No. 50-298/80-12

> Nebraska Public Power District ATTN: Mr. J. M. Pilant, Director Licensing and Quality Assurance P. O. Box 499 Columbus, Nebraska 68601

Gentlemen:

This refers to the inspection conducted by Mr. R. G. Spangler and Ms. M. J. Roberds of this office during the periods of August 18-21, 1980, of activities authorized by NRC Operating Licensee DPR-46, and to the discussions of the finding with Mr. L. C. Lessor.

Areas examined during the inspection and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Within the scope of this inspection, no items of noncompliance were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If the report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office within twenty (20) days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

G. L. Madsen, Chief

B3 Madri

Reactor Operations and Nuclear Support Branch

Enclosure: Inspection Report No. 50-298/80-12

cc w/enclosure

L. C. Lessor, Superintendent Cooper Nuclear Station P. O. Box 98 Brownville, Nebraska 68321