

U. S. NUCLEAR REGULATORY COMMISSION

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	3	3	7	1	0	0	5	8	0	8	1	1	0	3	8	0	9
60	61	ROCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

0 2 | While performing routine surveillance testing on October 5, 1980, the Drywell

0 3 | Equipment Drain Sump Integrator (20-FQ-530) and Flow Recorder (20-FR-528) were

0 4 | found inoperable. Technical Specification paragraph 3.6.D.2a allows operation for

0 5 | seven (7) days with this instrument (20-FQ-530) inoperable. No significant hazard

0 6 | existed.

0 7 |

0 8 |

SYSTEM CODE C I 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE T 15		VALVE SUBCODE Z 16							
EVENT YEAR 8 0 21 22		SEQUENTIAL REPORT NO. 0 7 8 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE 1 30		REVISION NO. 0 32									
ACTION TAKEN X 18		FUTURE ACTION C 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER G 0 8 0 26 44 47	

1 0 The flow transmitter (20-FT-364) was replaced and satisfactorily recalibrated

1 1 on October 6, 1980. No problem was found with the integrator or the recorder.

1 2 Replacement of the transmitter made the loop operable.

1 3

1 4

7	8	9	FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	28	1	0	0	29	NA	B	31	Surveillance Testing			32			
7	8	9	ACTIVITY CONTENT			AMOUNT OF ACTIVITY			LOCATION OF RELEASE								
1	6	Z	33	Z	34	NA	35	NA	36								
7	8	9	PERSONNEL EXPOSURES			DESCRIPTION											
1	7	0	0	0	37	Z	38	NA	39								
7	8	9	PERSONNEL INJURIES			DESCRIPTION											
1	8	0	0	0	40	NA	41										
7	8	9	LOSS OF OR DAMAGE TO FACILITY			DESCRIPTION											
1	9	Z	42	NA	43												
7	8	9	PUBLICITY			DESCRIPTION											
2	0	N	44	NA	45												
7	8	9	ISSUED			DESCRIPTION											
2	0	N	44	NA	45												

801106050/

NRC USE ONLY

NRC USE ONLY

W. Verne Childs

(315) 342-3840 X207