- AUCLEAR REQUE ONINO

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

September 30, 1980

TIC

In Reply Refer To: RIV Docket Nos. 50-445/IE Supplement No. 2 to Bulletin 79-01B 50-446/IE Supplement No. 2 to Bulletin 79-01B

Texas Utilities Generating Company ATTN: Mr. R. J. Gary, Executive Vice President and General Manager 2001 Bryan Tower Dallas, Texas 75201

Gentlemen:

The enclosed IE Supplement No. 2 to Bulletin 79-01B is forwarded to you for information. No written response is required. If you desire additional information regarding this matter, please contact this office.

Q

Sincerely,

Karl V. Seyfrit Director

Enclosures:
1. IE Supplement No. 2 to
 Bulletin No. 79-01B
2. List of Recently Issued

IE Bulletins

DUPLICATE

SSINS: 6820 Accession No.: 8008220241 IEB 79-01B, Suppl. 2

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

> IE Bulletin No. 79-01B Supplement No. 2 Date: September 30, 1980

ENVIRONMENTAL QUALIFICATION OF CLASS 1E EQUIPMENT

Enclosed are the generic questions and answers which resulted from NRC/Licensee meetings in NRC Regional Offices during the week of July 14, 1980 regarding environmental qualification of Class 1E equipment in use at power reactor facilities. These answers address specific questions asked during the meetings. Due to the generic nature of some of these questions, the staff is issuing them as a bulletin supplement. The regional meetings highlighted the fact that in some cases, the scope and depth of the 79-01B review was not clear to licensees. Therefore, these answers may affect your 79-01B submittal. These submittals are required by a separate order to be completed by November 1, 1980.

Some answers given in Supplement No. 1 to IEB-79-01B are superseded by these answers. For example, in Bulletin Supplement No. 1, issued on February 29, 1980, the answer to question No. 5 specified that TMI lessons learned equipment was not included in the review. However, due to the extension of the response date from April 14, 1980 to November 1, 1980, this equipment is now being addressed since its installation is either complete or required before the issuance of the February 1, 1981 SER. (See Question No. 21 of this Supplement.)

No specific response is requested by this Supplement; however, all answers contained in the enclosure to this Supplement should be carefully reviewed and considered for applicability in your response to IEB 79-01B.

IE Bulletin No. 79-01B was issued under a blanket GAO clearance (B180225 (ROO72); clearance expired July 31, 1980) specifically for identified generic problems. Supplement No. 2 to Bulletin 79-01B is for information, hence no GAO clearance is required.

Enclosures:

 Generic Questions and Answers to IEB79-01B and Memorandum and Order (CLI-80-21) dated May 23, 1980