

Commonwealth Edison Zion Generating Station Shiloh Blvd. & Lake Michigan Zion, Illinois 60099 Telephone 312/746-2084

1980 NOV 6 AM 10 03

November 3, 1980 US NAC DISTA STRUCT SERVICES

TRIBUTION

Mr. Darrel G. Eisenhut Director, Division of Licensing U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Reference: Zion Generating Station Docket No. 50-299/DPR-39 Environmental Technical Specification (Appendix B) Section 3.4

Dear Mr. Eisenhut:

Enclosed please find Reportable Occurrence Report No. 50-295/80-45 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 10-28-80.

This report is submitted to you in accordance with the requirements of the Environmental Technical Specifications, (Appendix B) Section 3.3.4 which states that violations of an environmental Technical Specification require a 10 day written report.

L. Graesser

Superintendent Zion Station

SG/tg

Enclosure: Reportable Occurrence Report No. 50-295/80-45

cc: J. Kohler/J. Waters J. Keppler