

APPENDIX A

NOTICE OF VIOLATION

Combustion Engineering, Inc.

Docket Nos. 70-1100  
30-03754

Based on the results of an NRC inspection conducted on July 9-11, 1980, it appears that one of your activities was not conducted in full compliance with the conditions of your license as indicated below. Item A is an infraction.

A. Condition No. 16 of License No. 06-00217-06 states,

"Except as specifically provided otherwise by this license, the licensee shall possess and use licensed material described in Items 6, 7, and 8 of this license in accordance with statements, representations, and procedures contained in applications dated February 24, 1978 and October 30, 1978."

Item No. 14 of the application dated February 24, 1978 states,

"A Radiological Control Committee has been organized to perform the following functions:

- a) Evaluate proposed changes in the handling of byproduct materials for personnel safety and protection of the environment.
- b) Perform an annual audit of all operations involving byproduct materials. The committee shall submit its findings and recommendations to the Vice-President for Development."

Contrary to the above, a Radiological Control Committee has not been organized to perform the intended functions.