

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 0 | R | T | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

CON'T
01 | 1 | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 4 | 4 | 7 | 1 | J | 2 | 8 | 8 | 0 | 8 | 1 | 0 | 1 | 1 | 8 | 0 | 9
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | NO. 80-22: IE BULLETIN 79-01B REVIEW RESULTED IN DISCOVERY OF FOLLOWING
03 | SAFETY-RELATED EQUIPMENT NOT MEETING ENVIRONMENTAL QUALIFICATION FOR
04 | INTENDED SERVICE: BARTON TRANSMITTERS (MODEL NOS. 345, 384, 389, 393).
05 | BURNS RTDs. NAMCO D2400X LIMIT SWITCHES, AND LIMITORQUE MOTOR OPERATORS.
06 | BACKUP EQUIPMENT OR ALTERNATIVE MONITORING IS AVAILABLE IF NECESSARY (SEE
07 | RESPONSE TO IE BULLETIN 79-01B DATED 9-5-80).

09 | Z | Z | 11 | X | 12 | Z | 13 | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
17 | 8 | 0 | 2 | 2 | 0 | 1 | T | 0 |
21 22 23 24 25 26 27 28 29 30 31 32
18 | X | 18 | A | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | N | 24 | Z | 25 | Z | 9 | 9 | 9 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | CHANGE IN CRITERIA FOR ENVIRONMENTAL QUALIFICATION OF SAFETY-RELATED
11 | EQUIPMENT REQUIRED BY IE BULLETIN 79-01B AND REVISED ORDER FOR MODIFICATION
12 | OF LICENSE (DATED 9-25-80) LED TO REVIEW AND DISCOVERY. EQUIPMENT WILL
13 | BE QUALIFIED TO MEET NEW CRITERIA OR REPLACED PRIOR TO 6-30-82.

15 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | 31 | NA | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

19 | Z | 42 | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

20 | N | 44 | NA | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER John C. Perry PHONE: 503/556-3713, ext. 228

8011070 526