

1200 NOV 17 AM 10 53



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

November 10, 1980

2-110-02

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

SUBJECT: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report No. 80-024/03X-1  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning the failure of the "A" spray train during Mode 3 operation. This is a revision of a previous report submitted May 20, 1980.

Very truly yours,

A handwritten signature in cursive script that reads "David C. Trimble".

David C. Trimble  
Manager, Licensing

DCT:GAC:lp

*ROY*  
Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

Mr. Norman M. Haller, Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

S 8011180 507