LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
1 N C B E P @ 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T REPORT
During the performance of Main Steam Line Isolation Valve Closure Channel Functional
[0]3 Test, P.T. 1.3.1P-2, when MSIV F028C was reopened main steam line "C" indicated
[0]4 minimum flow. It is believed that a stem-disc separation has occurred in the out-
[0 5 board MSIV on main steam line "C". Both MSIV's in main steam line "C" were then shut
0 6 and deactivated.
67
Technical Specifications 3.6.3, 6.9.1.9b
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
17 REPORT 8 1
At this time the exact cause of the minimum steam flow in main steam line "C" has not
been determined. An investigation will be performed during a future outage. A supple-
[1]2 ment to this report will be submitted following a determination and repair of the
1 3 problem causing this event.
114
FACILITY STATUS POWER OTHER STATUS OTHER
7 8 9 10 12 13 44 45 46 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8 9 11 12 13 80
NA NA NA NA
LOSS OF OR DAMAGE TO FACILITY 43
NA N
2 0 N 44 DESCRIPTION 45
NAME OF PREPARER M. J. Pastva, Jr. PHONE: 919-457-9521
8102170057