



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

May 20, 1975

Mr. Gaston Fiorelli, Chief
Reactor Operations Branch
Office of Inspection & Enforcement
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Dresden Station Unit 1 Response to Noncompliance
Items Continued in I.E. Inspection Report No.
75-010/75-05, NRC Docket No. 50-10

Dear Mr. Fiorelli:

I.E. Inspection Report No. 75-010/75-05, transmitted by your letter dated April 28, 1975, listed one infraction and two deficiencies. Your letter indicated that corrective action for the infraction reviewed by the inspector was adequate and a response was not required at this time.

Deficiency No. 1

The first deficiency concerned the lack of review of the jumper log and documentation of jumper removal.

Corrective Action

The Unit 1 jumper log was reviewed and all outstanding jumpers were field verified to determine which were still in place. The jumper log was updated to reflect the results of the field verification and also to include the most recent procedure. The log entry for jumper 14-74, which was found insufficient in detail, was corrected to include the exact location and reason for the jumper.

Also, a note was placed in the Daily Operating Orders to the Shift Engineers reminding them of the importance of review and sign off of the jumper log surveillance. These items were completed on May 8, 1975.

Action to Prevent Recurrence

Jumper log review presently is included in the Center Desk Surveillance routine. The shift supervisor sign-off for jumper log review will be transferred from the Center Desk Surveillance routine to the Unit Surveillance routines. Thus, the shift supervisor will initial the jumper log review at each unit (i.e. Unit 1, 2, and 3). This will assure jumper log review since it places the

8008280648

Mr. Gaston Fiorelli

May 20, 1975

surveillance requirement at the unit involved. This surveillance transfer will be completed by June 10, 1975.

Date of Full Compliance

Full compliance with the procedures was accomplished by completion of the corrective action. These items were completed on May 8, 1975. The actions to prevent recurrence will be completed by June 10, 1975.

Deficiency No. 2

The second deficiency concerned the delay in reporting an unusual event for 43 days instead of the required 30 days.

Corrective Action

Compliance with the reporting requirement was met with the submittal of the report, although 13 days late.

Action Taken to Prevent Recurrence


The circumstances of the event, from its initiation until the internal deviation report was instituted, will be reviewed by station management, in order to establish a system so that the reporting of any similar events will be incorporated into the plant reporting routine.

Date of Full Compliance

Full compliance was achieved with the submittal of the unusual event report. The action taken to prevent recurrence will be completed by May 23, 1975.

Your inspection report has been reviewed for proprietary data and none was identified.

Sincerely,


Byron Lee, Jr.
Vice President