



**Commonwealth Edison**

One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

March 14, 1977

Mr. James G. Keppler, Director  
Directorate of Inspection and  
Enforcement - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: Dresden Station Units 1, 2, and 3  
Response to IE Inspection Nos.  
50-10/77-02, 50-237/77-02, and  
50-249/77-02  
NRC Docket Nos. 50-10, 50-237, and 50-249

Reference (a): J. M. Allan (NRC) letter to Byron Lee (CECO)  
dated February 25, 1977.

Dear Mr. Keppler:

Attached is the response to the item listed under Infraction  
in the enclosure to Reference (a).

Neither this response nor the original report contain  
proprietary information.

Please address any additional questions on this matter to  
this office.

Very truly yours,

A handwritten signature in cursive script that reads 'R. L. Belger'.

R. L. Belger  
Assistant Vice President

Attachment

8009020572

MAR 16 1977

### INFRACTION

Failure to insure that the control room copy of GSEP and the telephone directory contained the most recent revision.

### DISCUSSION OF INFRACTION

During a routine emergency planning inspection conducted on February 2, 3, 4, and 7, 1977, the NRC inspector noted that the Control Room copy of GSEP and the GSEP telephone directory did not contain the most recent applicable revisions. The most recent revisions had been issued in October, 1976, and distributed during November and December as they became available from the printer. Each GSEP copy is sent with a cover letter, to be returned to the GSEP Coordinator, confirming that the revision has been received. Since the cover letter for the Control Room copy was never returned, it was determined that the Control Room GSEP copy was either lost in the mail or upon receipt at the station. A follow-up to confirm that all cover letters were returned was delayed by a personnel change in the GSEP coordinator position.

### CORRECTIVE ACTION

A copy of the latest revision of GSEP and the telephone directory was requested from the GSEP Coordinator during the inspection. This copy was received at the station and incorporated in the Control Room copy on February 10, 1977.

### CORRECTIVE ACTION TO AVOID RECURRENCE

A discussion was held with the new GSEP coordinator to assure that this type of incident would not recur. It was agreed between the GSEP coordinator and the station that follow-ups on the cover letters would be more timely. Station GSEP revision distribution procedures were reviewed and found to be adequate.

### DATE OF FULL COMPLIANCE

The Station achieved full compliance as of February 10, 1977.