

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
1750 Chestnut Street Tower II

October 15, 1980

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DFR-77 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-327/80135 REVISION 1

The enclosed report is a supplement to my letter dated August 14, 1980,  
concerning ice condenser inlet doors which were opened due to a differential  
pressure created by both lower compartment doors inadvertently being  
opened at the same time. This report is submitted in accordance with  
Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. W. T. Cottle, NRC Inspector, Sequoyah

8010210 635

S

A002  
S, 11