

PILGRIM NUCLEAR POWER STATION
RFD #1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

September 30, 1980

BECo Ltr. #80-249

Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Licensee Event Report 80-068/03L-0

Docket Number 50-293
License DPR-35

Gentlemen:

The attached Licensee Event Report 80-068/03L-0, "Failure to Log Reactor Protection M.G. Set Current and Voltage Once Per Shift", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.c. This Licensee Event Report is being reissued as No. 80-068/03L-0 to change its report number previously issued on September 30, 1980 as No. 80-066/03L-0.

If there are any questions on this subject, please contact us.

Respectfully submitted,



R. D. Machon
Nuclear Operations Manager
Pilgrim Station

MTM:ep

Enclosures: (3 copies)

LER 80-068/03L-0

cc: Director (40 copies)

Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555