BOSTON Edison COMPANY

PILGRIM NUCLEAR POWER STATION RFD #1 ROCKY HILL ROAD PLYMOUTH, MASSACHUSETTE 02360

October 10, 1980

BECo Ltr. #80-250

Director, Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

> Docket Number 50-293 License DPR-35

Licensee Event Report 80-067/01T-0

Gentlemen:

. . .

The attached Licensee Event Report 80-067/01T-0, "Pipe Anchor", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.l.h. The Operations Review Committee has reviewed this event and classified it as an error in the methods used for such analysis as described in the Safety Analysis Report.

If there are any questions on this subject, please contact us.

Respectfully submitted,

. M 7.10

R. D. Machon Nuclear Operations Manager Pilgrim Station

ETG:ep

Enclosures: (3 copies) LER 80-067/01T-0

cc: Director (40 copies)
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555