

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A R A N 0 2 0 0 - 0 0 0 0 - 0 0 4 1 1 1 1 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T
01 L 0 5 0 0 0 3 6 8 7 1 0 0 7 8 0 1 1 0 5 8 0
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

REPORT SOURCE: L 0 5 0 0 0 3 6 8 7 1 0 0 7 8 0 1 1 0 5 8 0
60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 During Mode 1 operation, the "A" Safety Injection Tank (SIT) pressure
03 was found to be less than 600 psia (597 psia) per Tech. Spec. 3.5.1.d.
04 SIT's "B", "C", and "D" were verified to have the proper level and pres-
05 sure per T.S. 3.5.1. This occurrence is similar to LER 50-368/79-016.
06 Reportable per Tech. Spec. 6.9.1.9.b.
07
08
09

SYSTEM CODE: SIF 11 CAUSE CODE: E 12 CAUSE SUBCODE: B 13 COMPONENT CODE: V A L V E X 14 CONTR. NUMBER: C 15 VALVE FORCODE: A 16
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LER-NO. REPORT NUMBER: 18 0 EVENT YEAR: 8 0 SEQUENTIAL REPORT NO.: 0 7 5 OCCURRENCE CODE: 0 3 REPORT TYPE: L REVISION NO.: 0
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTION TAKEN: E 18 FUTURE ACTION: Z 19 EFFECT ON PLANT: Z 20 SHUTDOWN METHOD: Z 21 HOURS: 0 0 0 0 ATTACHMENT SUBMITTED: N 23 NPRO-4 FORM SUB: N 24 PRIME COMP SUPPLIER: N 25 COMPONENT MANUFACTURER: V 0 8 5
32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 The low pressure was attributed to a volume loss due to sampling without
11 the capability of remote repressurization due to an inoperable control
12 valve (2CV-5005). The N₂ overpressure was restored by manually opening
13 the N₂ supply valve from inside the containment. The "A" SIT was returned
14 to operable status meeting requirements of T.S. 3.5.1 Action a.
15 2CV - 5005 has been repaired.
16 E 28 1 0 0 0 29 Power Ops A 31 During Routine SIT sampling
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY: Z 33 CONTENT: Z 34 AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL EXPOSURES: 0 0 0 37 TYPE: Z 38 DESCRIPTION: NA
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PERSONNEL INJURIES: 0 0 0 40 TYPE: NA DESCRIPTION: NA
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

LOSS OF OR DAMAGE TO FACILITY: Z 42 TYPE: NA DESCRIPTION: NA
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PUBLICITY: N 44 DESCRIPTION: NA
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ISSUED: N 44 DESCRIPTION: NA
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER: Rex Pendergraft PHONE: 501/968-2519

8011140033