

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE BOX 784

COLUMBIA, SOUTH CAROLINA 29218

T. C. NICHOLS, JR.
VICE PRESIDENT AND GROUP EXECUTIVE
NUCLEAR OPERATIONS

December 23, 1980

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street, N. W.
Atlanta, Georgia 30303

Subject: Virgil C. Summer Nuclear Station
Potential Significant Deficiency,
Interim Report - 10CFR50.55(e)
Nuclear Engineering File 3.1051
Docket No. 50/395


Dear Mr. O'Reilly:

On November 26, 1980, Mr. Bob McFarland of NRC Region II was notified of a potential significant deficiency on the subject: Seismic Installation Not Inspected. The report was made by Mr. J. A. Wactor.

The equipment involved is non-safety related relay cabinets in the relay room. The cabinets were required to be seismically mounted since there are safety related cabinets in the same room. There was no documentation that the installation had been inspected.

The cabinet mountings have been reinspected, and some minor discrepancies are being evaluated by structural engineering. The evaluation is expected to be complete by January 23, 1981, and a final report issued thereafter.

Very truly yours,



T. C. Nichols, Jr.

JAW:TCN:glb

cc: B. A. Bursey
V. C. Summer
G. H. Fischer
W. A. Williams, Jr.
T. C. Nichols, Jr.
E. H. Crews, Jr.
D. A. Nauman
O. S. Bradham
O. W. Dixon, Jr.
J. B. Knotts, Jr.

R. B. Clary
A. R. Koon
A. A. Smith
J. L. Skolds
I&E (Washington)
Document Management Branch
(55e/21/LER Only)
NPCF/Whitaker
File

*Boia
5/10*

8012300628

5