

The

BOSTON EDISON COMPANY
GENERAL OFFICES 800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

A. V. MORISI
MANAGER
NUCLEAR OPERATIONS SUPPORT DEPARTMENT

December 5, 1980

BECO. Ltr. #80-306

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA. 19406

License No. DPR-35
Docket No. 50-293

Response to IE Bulletin #80-21

Dear Sir:

By letter dated November 6, 1980, you transmitted IE Bulletin No. 80-21, "Valve Yokes Supplied by Malcolm Foundry Company, Inc." Boston Edison Company was requested to review the following for applicability at Pilgrim Station:

Item 1

Determine if any of the active valves in use or planned for use in safety-related systems at your facility have valve parts cast by Malcolm Foundry Company, Inc. If no valves are identified as having potentially faulty material, indicate that this is the case and ignore the remaining questions.

Response

Pilgrim Station does not have in use or planned for use in safety-related systems any valve yokes supplied by Malcolm Foundry Company, Inc.

Very truly yours,

Amorisi

810 1140 927

Q