



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

DEC 26 1980

Docket No. 50-29
LS05-80-12-044

Mr. James A. Kay
Senior Engineer - Licensing
Yankee Atomic Electric Company
25 Research Drive
Westborough, Massachusetts 01581

Dear Mr. Kay:

SUBJECT: YANKEE ROWE - SEP TOPIC III-3.8, STRUCTURAL AND OTHER CONSEQUENCES
(E.G. FLOODING OF SAFETY RELATED EQUIPMENT IN BASEMENTS) OF
FAILURE OF UNDERDRAIN SYSTEMS

This letter is to advise you that Topic III-3.8, "Structural and Other Consequences (e.g. Flooding of Safety Related Equipment in Basements) of Failure of Underdrain Systems" has been deleted from the Systematic Evaluation Program (SEP) review of your facility.

The topic is not applicable to your site because your site does not have a system whose function is to lower the groundwater table.

Please review and provide your comments within 30 days of the date you receive this letter. If no response is received within that time, we will assume that you have no comments or corrections.

Sincerely,

Dennis M. Crutchfield
Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Licensing

cc: See next page

8101270158

Mr. James A. Kay

YANKEE-ROWE ATOMIC
POWER STATION
DOCKET NO. 50-29

cc
Mr. James E. Tribble, President
Yankee Atomic Electric Company
25 Research Drive
Westborough, Massachusetts 01581

Greenfield Community College
1 College Drive
Greenfield, Massachusetts 01301

Chairman
Board of Selectmen
Town of Rowe
Rowe, Massachusetts 01367

Energy Facilities Siting Council
14th Floor
One Ashburton Place
Boston, Massachusetts 02108

Director, Technical Assessment
Division
Office of Radiation Programs
(AW-459)
U. S. Environmental Protection
Agency
Crystal Mall #2
Arlington, Virginia 20460

U. S. Environmental Protection
Agency
Region I Office
ATTN: EIS COORDINATOR
JFK Federal Building
Boston, Massachusetts 02203

Resident Inspector
Yankee Rowe Nuclear Power Station
c/o U.S. NRC
Post Office Box 28
Monroe Bridge, Massachusetts 01350