

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

1981 JAN 25 PM 12 50
REGISTRATION
SERVICES
January 21, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

One Steam Exclusion Setpoint Drifted
Out of Specification

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2(a) since it represents discovery of an engineered safety feature instrument setting less conservative than required by the technical specifications.

Yours very truly,


L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

-over-

810 1270 635

S