



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, N.C. 28461

Company Correspondence

September 18, 1980

FILE: B09-13514

SERIAL: BSEP/80-1520

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2  
LICENSE NOS. DPR-71 AND DPR-62  
DOCKET NOS. 50-325 AND 50-324  
SUPPLEMENT TO IE INSPECTION REPORT 50-324/80-24 AND 50-325/80-27

Dear Mr. O'Reilly:

During a telephone conversation between plant personnel and Mr. B. T. Moon, of your office, on July 16, 1980, concerning Item 6C of IE Inspection Report 50-324/80-24 and 50-325/80-27, the Brunswick Steam Electric Plant (BSEP) made a commitment to provide corrective actions including procedure revisions for future testing by September 30, 1980. Due to the manpower requirements which resulted from IE Bulletin 79-01B, IE Bulletin 80-17 and the subsequent problems found with the Control Rod Drive (CRD) supports and baseplates, this commitment cannot be completed until December 12, 1980. The overall commitment to resolve the total concerns before the performance of the next scheduled test will be met.

Should you have any questions on this matter, please contact me or a member of my staff.

Very truly yours,

A. C. Tollison, Jr., General Manager  
Brunswick Steam Electric Plant

RMP/jal

cc: Mr. R. A. Hartfield  
Mr. V. Stello, Jr.

OFFICIAL COPY

Q 8101270 873