

TIC

ILLINOIS POWER COMPANY



U-0210  
L08-81(01-08)-6  
500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525  
January 8, 1981



Mr. James G. Keppler  
Director, Region III  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Clinton Power Station Units 1 & 2  
Docket Nos. 50-461 and 50-462  
Construction Permits No. CPPR-137 & CPPR-138

This is in reply to your letter of November 6, 1980, whereby you forwarded IE Bulletin No. 80-21 which reported on the failures of some valve yokes supplied by Malcolm Foundry Co., Inc.

Please be advised that Illinois Power is still pursuing the initial determination on valve parts required by item 1 of the bulletin. Some of our vendors investigations are still not complete. We propose to provide a complete response to the bulletin action items by the end of February 1981.

Sincerely,

G. E. Wuller  
Supervisor - Licensing  
Nuclear Station Engineering

GEW/em

cc: H. H. Livermore, NRC Resident Inspector  
Director, Office of I & E, Div. of Reactor Operations Inspection  
NRC, Washington, D. C.

8101280 600

JAN 12 1981