



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

January 21, 1981

Docket Nos. 50-445/80-22
50-446/80-22

Texas Utilities Generating Company
ATTN: Mr. R. J. Gary
Executive Vice President
and General Manager
2001 Bryan Tower
Dallas, Texas 75201



Gentlemen:

This refers to the investigation conducted by Mr. D. D. Driskill and Mr. T. Digaloma of our staff on September 8-11 and November 6-7, 1980, at your facility in Glen Rose, Texas, concerning allegations that Brown & Root quality assurance department was not ensuring that corrective action was being taken regarding documented nonconformances, that NCR's were being disapproved and the numbers issued for the respective disapproved NCR drafts were being re-used and that discrepancies identified in vendor-manufactured components were being waived in order that the equipment could be shipped to CPSES. The investigation and our findings are discussed in the enclosed investigation report.

In accordance with Section 2.790 of the Commission's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter together with the enclosed investigation report will be placed in the Commission's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you make a written application within twenty (20) days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this investigation, we will be pleased to discuss them with you.

Sincerely,

Karl V. Seyfrit
Director

Enclosure:
Investigation Report
Nos. 50-445/80-22
50-446/80-22

8108040 437