

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 11, 1980

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Inadequate Installation of NAMCO Limit Switches

Three copies of the Licensee Event Report for this occurrence are enclosed.

This event is reported in compliance with Technical Specification 6.7.B.2(c) because inadequate instructions were provided for installing safety related instrumentation. Reporting was recommended by our NRC Resident Inspector.

Yours very truly,


L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/bd

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

8012150 191

5