



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 8008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

December 23, 1980

D. L. ASWELL
Vice President-Power Production

W3K80-0036
Q-3-A35.07

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Potential Construction Deficiency No. 33
"Control Element Drive Mechanism Motor Housings (Class I Vessels)
Manufactured Without Final Surface Penetrant Non-Destructive
Examination"

REFERENCE: Telecon - L. L. Bass (LP&L) to R. C. Stewart - November 26, 1980

Dear Mr. Seyfrit:

In the referenced telecon, we indicated that we were evaluating the reportability of the subject deficiency under 10CFR50.55(e). We have completed our evaluation and have determined that this deficiency is not reportable. The results of our review are on file at the Waterford SES Unit No. 3 site and are available for your inspection.

Very truly yours,

D. L. Aswell

DLA/TFG/ncd

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

*Boia
S/O*

8012800 581

5