



Consumers
Power
Company

James W Cook
Vice President - Projects, Engineering
and Construction

General Offices: 1945 West Parnell Road, Jackson, MI 49201 • (517) 788-0453

February 13, 1981

Mr J G Keppler, Regional Director
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND PROJECT - DOCKET NOS 50-329, 50-330
ASSIGNMENT OF NRC CONTROL NUMBERS
TO 50.55(e) REPORTS FILE: 0.4.9 UFI: 73*10*01 SERIAL: 11192

Reference: (1) J G Keppler letter to J W Cook, dated January 22, 1981

In response to your request (Reference 1), we have given NRC Assigned Numbers to all Consumers Power 50.55(e) reports, beginning with our very first report made in 1973 to our most recent report made January 22, 1981. A listing of all our 50.55(e) reports and their corresponding numbers is provided in Attachment 1 to this letter. We will begin showing these NRC Assigned Numbers in the upper right hand corner of all future 50.55(e) correspondence.

James W. Cook

WRB/lr

CC: Director, Office of Inspection & Enforcement
US Nuclear Regulatory Commission
Att Mr Victor Stello (15)

~~Director, Office of Inspection & Enforcement~~
Information & Program Control, USNRC (1)

RJCook, USNRC Resident Inspector
Midland Nuclear Plant (1)

*Bo 19
5/1*

S

8102180 499

2
Serial 11192

CC: CBechhoefer, ASLB Panel
GALinenberger, ASLB Panel
FPCowan, ASLB Panel
AS&L Appeal Panel
MMCherry, Esq
MSinclair
CRStephens, USNRC
WDPaton, Esq, USNRC
FJKelly, Esq, Attorney General
SHFreeman, Esq, ASst Attorney General
GTTaylor, Esq, Asst Attorney General
WHMarshall
GJMerritt, Esq, TNK&J
Great Lakes QA Managers

LOG 50.55(e) ITEMS

NRC ASSIGNED NO.	FILE NO.	DESCRIPTION	MCAH NO. IF APP.	DATE REPORTED	DATE NEXT CPCO REPORT DUE	DATE CPCO FINAL REPORT	DATE CFCO CLOSE OUT	DATE & LETTER NRC CLOSEOUT
73-01	0.4.9.2	B&W Weld Filler Certification		01/16/73		02/12/73		08/22/79 (2) IE Report 79-15, Pg 4
73-02	0.4.9.3	Cadwelds		11/09/73		12/10/73		(2) NRC Ltr of 12/26/73
73-03	0.4.9.4	B&W Prototype Testing		12/28/73		03/01/74		01/04/80 (2) IE Report 79-25, Pg 5
74-01	0.4.9.5	Containment Fire		11/21/74		01/21/75		(3) NRC Ltr of 02/06/75
74-02	0.4.9.6	Containment Rebar Spacing		12/05/74		04/23/75		(3) NRC Ltr of 05/07/75
76-01	0.4.9.7	Missing Rebar		04/13/76		05/21/76		
76-02	0.4.9.8	B&W Surveillance Capsule Holder		04/13/76		05/27/77		06/21/77 NRC Ltr of 06/21/75 (4)
76-03	0.4.9.9	Component Cooling Water Pump Casing	13	12/10/76		05/27/77		The order for this component was cancelled.
77-01	0.4.9.10	Liner Plate Bulge	16	02/28/77		08/15/78	12/78 (1)	
(1) Includes any modifications of installation after design release. (2) Letter of R H Engelben (NRC) to J F Malla (B&W) of April 24, 1973 accepts the steam generators for service. (3) Letter of J G Davis (NRC) to S H Howell acknowledges report and states "should we require additional information..., we will contact you." (4) Letter of R F Heishman (NRC) to S H Howell "...this closes our control No. F31289F3, previously H01289F3."								

LOG 50.55(e) ITEMS

NRC ASSIGNED NO.	FILE NO.	DESCRIPTION	MCAR NO. IF APP.	DATE REPORTED	DATE NEXT CPCO REPORT DUE	DATE CPCO FINAL REPORT	DATE CPCO CLOSE OUT	DATE & LETTER NRC CLOSEOUT
77-02	0.4.9.11	Tendon Sheath	17	04/19/77		08/12/77	10/78 (1)	IE Report 79-15 Pg 4
78-10	0.4.9.22	Qualification Test Review	25	11/13/78	03/27/81			
78-11	0.4.9.23	Pressurizer Heater System		12/07/78	04/01/81			
78-12	0.4.9.24	Penetrations, Termination Defects	26	12/22/78		05/25/79	06/08/79 (1)	
78-13	0.4.9.25	Control Room Air Filter System Inadequate Wiring	27	12/27/78		03/09/79	01/80	
79-02	0.4.9.27	Feedwater System Pipe Spool - Impact Properties	29	05/22/79		12/10/79		
79-01	0.4.9.26	Main Control Status Display Panels (Soldered Connections)	28	05/29/79		07/20/79		
79-07	0.4.9.32	Containment Air Coolers, Cooling Water, Supply Pressure	30	07/09/79		10/15/79		
79-03	0.4.9.28	Small Break/RC Pump Operation Interaction	NA	07/16/79	05/30/81			
79-04	0.4.9.29	States Sliding Links, Defective Clip Presents Cinching	32	07/19/79		03/03/80		
79-05	0.4.9.30	Tendon Wire Length Variation	33	07/27/79		10/31/79		
77-03	0.4.9.12	ITF Grinnell Pipe Supports	NA	10/27/77		09/08/78		
78-01	0.4.9.13	RCP Motor Flange	NA	01/18/78		01/31/79		
78-03	0.4.9.15	Personnel Air Locks	20	02/02/78		09/29/78		
								02/16/80 Closed in I&E Report 80-01 Page 16/17

LOG 50.55(e) ITEMS

NRC ASSIGNED NO.	FILE NO.	DESCRIPTION	MCAR NO. IF APP.	DATE REPORTED	DATE NEXT CP-CO REPORT DUE	DATE CP-CO FINAL REPORT	DATE CP-CO CLOSE OUT	DATE & LETTER NRC CLOSEOUT
78-02	0.4.9.14	Decay Heat Removal Pumps	NA	02/02/78		08/02/78	08/78	12/28/78 NRC Report 78-15
78-04	0.4.9.16	RPS Loss of Ground	NA	03/08/78		01/11/80		
78-05	0.4.9.17	Spray Piping Supports	22	03/22/78		12/21/79		
78-06	0.4.9.18	Small Break Analysis	NA	04/12/78		03/12/79		
78-07	0.4.9.19	Seismic Cable Tray Supports	23	04/14/78		09/08/78		
78-08	0.4.9.20	Diesel Generator Building Foundation		09/07/78		02/07/80		Transferred to Licensing to follow.
78-09	0.4.9.21	Battery Racks	NA	10/20/78		01/31/79		
79-06	0.4.9.31	Station Batteries	NA	08/01/79		08/23/79		
79-08	0.4.9.33	Hilti Drop-In Anchors	NA	08/31/79		12/21/79		
79-10	0.4.9.35	RV Anchor Bolt Failure	37	08/31/79	3/31/81			
79-11	0.4.9.36	Boration System Inadequacies	NA	10/02/79	7/17/81			
79-12	0.4.9.37	Unit 2 Shield Wall Coatings	35	11/13/79	3/1/81			
80-01	0.4.9.38	Letdown Cooler Supports	NA	02/26/80	4/15/81			
79-09	0.4.9.34	Gould Part 21	NA	09/21/79		10/15/79		
80-02	0.4.9.39	B&W/Bechtel Inconsistencies on Cross-Referencing for B&W Supplied Items	38	05/02/80		10/31/80		
80-03	0.4.9.40	ECC Actuation System Cross-over	39	06/18/80		07/17/80		

LOG 50.55(e) ITEMS

NRC ASSIGNED NO.	FILE NO.	DESCRIPTION	MCAR NO. IF APP.	DATE REPORTED	DATE NEXT CPCO REPORT DUE	DATE CPCO FINAL REPORT	DATE CPCO CLOSE OUT	DATE & LETTER NRC CLOSEOUT
80-04	0.4.9.41	HELBA Restraint Design	40	8/21/80	4/3/81			
80-05	0.4.9.42	Sway Strut Rod Ends Deficiency	42	9/24/80	2/27/81			
80-06	0.4.9.43	Component Cooling Water Design	43	10/8/80	3/31/81			
80-07	0.4.9.44	Reactor Coolant Loop Analysis	44	11/17/80	3/12/81			
80-08	0.4.9.45	ECCAS Cabinets		11/18/80	2/27/81			
80-09	0.4.9.46	Low Alloy, Quenched & Tempered Bolting 7/8" Dia and Greater	45	11/26/80	3/31/81			
81-01	0.4.9.47	Limiter Operator - Terminal Strip Voltage Rating	46	1/14/81	2/13/81			
81-02	0.4.9.48	Seismic Model of Auxiliary Building	47	1/21/81	2/20/81			
81-03	0.4.9.49	Borated Water Storage Tank Foundation	48	1/22/81	2/21/81			