

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

March 17, 1981

SQRD-50-328/81-04



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30301

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 - ENVIRONMENTAL QUALIFICATION OF SAFETY-RELATED ELECTRICAL EQUIPMENT - SQRD-50-328/81-04 - THIRD INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on December 8, 1980, in accordance with 10 CFR 50.55(e) as NCR SQN EEB 8044R1. Interim reports were submitted on January 8 and February 12, 1981. We expect to submit our next report by April 3, 1981.

TVA is still continuing its investigation of the ASCO Model HTX8320A22V solenoids in the Radiation Monitoring System to determine whether the subject valves should be either repaired, relocated, or replaced.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
s
1/0