TENNESSEE VALLEY AUTHORITYSO R

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

January 13, 1981

81-004-032

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET NG. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE REPORT BFRO-50-296/8056

The enclosed report provides details concerning a diesel generator voltage available relay which was found dropped out all the time. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure (3)

cc (Enclosure): Director (3)

> Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Director (40) Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry