

U. S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

Report No. 50-213/80-01

Docket No. 50-213

License No. DPR-61

Category C
Safeguards Group IV

Licensee: Connecticut Yankee Atomic Power Company

P. O. Box 270

Hartford, Connecticut 06101

Facility Name: Haddam Neck

Inspection At: Haddam Neck, Connecticut

Inspection Conducted: January 8-11, 1980

Date of Last Physical Security Inspection Visit: October 15-19 and 24-26, 1979

Type of Inspection: Unannounced Physical Security

Inspectors: Richard H. Ladun
R. H. Ladun, Physical Security Inspector

2-4-80
date

W. Madden
W. Madden, Physical Security Inspector

2-4-80
date

Approved by: J. W. Devlin
J. W. Devlin, Chief, Security and Investigation
Section, Safeguards Branch

date
2-11-80
date

Inspection Summary:

Areas Inspected: Security Organization; Physical Barriers (Protected Area); Physical Barriers (Vital Area); Lighting; Access Control (Identification, Authorization, Badging); Access Control (Vital Areas); Communications; and, Compensatory Measures. The inspection involved 54 inspector-hours onsite by two regional based inspectors. The inspection was initiated during off hours; 10 inspector-hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements in the eight (8) areas examined except for the following three items:

1. Access Controls (Vital Area) - A vital area door was found unlocked and unattended (Infraction).
2. Compensatory Measures - Failure to maintain surveillance of protected area barriers and an exterior vital area door (Infraction).
3. Communications - Failure to equip fixed security patrols with portable radios (Infraction).