YANKEE ATOMIC ELECTRIC COMPANY 20 TURNPIKE ROAD, WESTBOROUGH, MASSACHUSETTS 01581 TELEPHONE 617 366-9011 January 23, 1973 United States Atomic Energy Commission Directorate of Regulatory Operations, Region I 970 Broad Street Newark, New Jersey 07102 Attention: Robert T. Carlson, Chief Facility Operations Branch Reference: License No. DPR-3 (Docket No. 50-29) Gentlemen: With reference to your letter dated January 18, 1973 relative to an inspection conducted by Mr. Oberg at Yankee Rowe on December 11-15, 1972, Yankee Atomic Electric Company offers the following reply to Item No. 2 of the violation: 1. The brass fittings were removed from the low pressure safety injection pump on December 19, 1972 and shall be replaced with fittings that comply with ANSI B31.7. 2. A plant management directive has been issued to re-establish the requirements for conformance with applicable codes, regulatory requirements and quality assurance requirements. We trust that this information is complete and satisfactory; however should you desire additional information feel free to contact us. Very truly yours, YANKEE ATOMIC ELECTRIC COMPANY L. H. Heider Manager of Operations GCA/kg 8011180 666