

UNITED STATES ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATIONS REGION 1

970 BROAD STREET NEWARK, NEW JERSEY 07102

RO Inquiry Report No. 50-29/72-110

Licensee:

Yankee Atomic Electric Company

License No.:

DPR-3

Docket No .:

50-29

Facility:

Yankee Rowe

Descriptive Title: Type "B" - Loss of Facility

Prepared by:

12/6/23

Baunack, Reactor Inspector

A. Date and Manner AEC was Informed:

December 4, 1972, by telephone call from the licensee.

B. Description of Particular Event or Circumstance:

The licensee informed RO, Region I, of his proposed action with regard to the problem experienced with the control rod shrouds. (RO Inquiry Report No. 50-29/72-10Q)

The decision has been made to replace the 32 control rod shroud tubes with a new unitized package bolted to the lower core support plate. This will necessitate the disassembly, removal, and disposal of the existing structure. The estimated time of completion of the modification is the end of April, 1973.

C. Action by Licensee:

The licensee has contracted with Westinghouse for the design and construction of the shroud tube package.

MEMO ROUTE SE		See me about this. For concur i.e. For action. For information.
J. G. Keppler, RO (2)	INITIALS	RO INQUIRY REPORT NO. 50-29/72-110
	DATE	YANKEE ATOMIC ELECTRIC CO. DOCKET NO. 50-29
TO (Name and unit)	PUTIALS	ACKAIKS
RO: NO (5) DR Central Files Reg. Standards (3)	223	The subject inquiry report is forwarded for
	ATE	your information. Distribution will be made
Dir of Licensing		by this office to the PDR, LPDR, NSIC, DTIE
TO (Name and unit)	INITIALS	and State representatives after review by the
	DATE	licensee for proprietary information.
FROM (Name and unit)	REMARKS	
70.10		
R. T. Carlson, RO:I		
PHONE NO. DATE 12/6/72		

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO: 1971 0 - 445-45