YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367

June 3, 1977

Mr. J. P. O'Reilly, Director U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 50-29/77-25/03L Loop Seal Radiation Monitor Failure

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Section 6.9.4.b, the attached Licensee Event Report is hereby submitted.

Very truly yours,

No a anto

H. A. Autio Plant Superintendent

RMM/mid

Enclosure:

- cc: [30] Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555
 - [3] Director, Office of Management Information & Program Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555

8011240 206

Regulatory Docket File

