

DISTRIBUTION
SERVICES UNIT

NSP

1980 NOV 25 PM 2:35 NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

NSP
DISTRIBUTION SERVICES
BRANCH

November 21, 1980

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-306 License No. DPR-60

Inoperability of No. 122 Auxiliary Building Special Vent System

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2(b) since it represents operation in a degraded mode permitted by the limiting conditions for operation.

Yours very truly,

David M. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/bd

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

-over-

8011260/81

S