



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

November 20, 1980

2-110-25

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

SUBJECT: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report No. 79-033/01X-1
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.8.c, attached is the subject report concerning an unisolatable leak discovered in the seal cavity pressure sensing line for a Reactor Coolant Pump. This is a revision to a previous report submitted May 25, 1979.

Very truly yours.

Donald A. Ricketts
for David C. Trimble
Manager, Licensing

DCT:GAC:lp

Woy
Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D.C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Comm.
Washington, D.C. 20555

8012010315