



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

November 21, 1980

1-110-21


Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

SUBJECT: Arkansas Nuclear One - Unit 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report No. 80-016/03X-2  
(File: 0520)


Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.b, attached is the subject report concerning the failure to obtain proper flow through the hydrogen purge system during surveillance testing. This is an update of a previous report submitted August 27, 1980.

Very truly yours,

  
for David C. Trimble  
Manager, Licensing

DCT:GAC:lp

  
Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

Mr. Norman M. Haller, Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

8012010

399

5