

ARKANSAS POWER & LIGHT COMPANY POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

October 16, 1980

CENTRAL FILES PDR:HO 70R TIC NSIC

STATE

1-100-10 2-100-12

K. V. Seyfrit, Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Comm. Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

> Subject: Arkansas Nuclear One - Units 1 & 2 Docket Nos. 50-313 and 50-368 License Nos. DPR-51 and NPF-6 IE Bulletin No. 79-17, Rev. 1 Pipe Cracking in Stagnant Borated Water Systems

(File: 1510.1, 2-1510.1)

Gentlemen:

This letter is to inform you that, in accordance with item 2 of the subject bulletin, all required piping inspections were completed as of October 10, 1980.

We are currently preparing a written report describing the results of these inspections. As required by item 6 of the bulletin, we will submit this report to you no later than November 9, 1980.

Very truly yours,

David & Timble David C. Trimble Manager, Licensing

DCT: DRH: 1p

cc: Division of Reactor Inspection Programs Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D.C. 20555

> Mr. W. D. Johnson U. S. Nuclear Regulatory Commission 8012120 09.9 P. O. Box 2090

Russellville, AR. MEMBER MIDDLE SOUTH UTILITIES SYSTEM